

Umrechnung Tabelle GA in mm²

ga	mm ²		ga	mm ²
1	7,350		16	1,290
2	6,540		17	1,150
3	5,830		18	1,024
4	5,190		19	0,912
5	4,620		20	0,812
6	4,110		21	0,723
7	3,670		22	0,644
8	3,260		23	0,573
9	2,910		24	0,511
10	2,590		25	0,455
11	2,300		26	0,405
12	2,050		27	0,361
13	1,830		28	0,321
14	1,630		29	0,286
15	1,450		30	0,255

www.smokewolke.de YouTube Smokewolke